Stanvac®

REFINERY & PETROCHEMICALS

MAJOR FIRE INCIDENTS IN INDIA.

Protect circuits. Protect people.

STANVAC FIREX EC 43 SURVIVAL



REPORTED INCIDENTS · 7

01 / 20 APR 2026

Connected units isolated.

HPCL Rajasthan Refinery | Pachpadra, Balotra · Rajasthan

Heat-exchanger-stack fire; no casualties reported. HPCL suspected a hydrocarbon leak at a valve or flange; cause under investigation.

The Economic Times · 21 Apr 2026

---

02 / 30 JUN 2026

12 fire engines responded.

Haldia Petrochemicals | Purba Medinipur · West Bengal

Pipeline fire injured at least 20 people, five critically, in AP's initial report. Cause unknown.

Associated Press · 30 Jun 2026

---

03 / 11 NOV 2024

Fatal storage-tank fire.

IndianOil Gujarat Refinery | Vadodara · Gujarat

Two people died and two were injured, according to Reuters.

Reuters · 13 Nov 2024

WHY EC 43 SURVIVAL?

WHEN CABLES FAIL, SAFETY SYSTEMS CAN FAIL.

Fire can disable the cables powering safety systems.

FIRE SUPPRESSION

Fire pumps. Firefighting controls.

HUMAN SAFETY

Alarms. Smoke extraction. Evacuation.

Protect critical circuits with EC 43 SURVIVAL.

Tested protection to help keep circuits working during fire.

Tests & application requirements

REQUEST A QUOTATION

sales@stanvac.com | +91 85271 99811

MORE REPORTED INCIDENTS

HPCL Visakhapatnam Refinery

19 SEP 2025 | Visakhapatnam · Andhra Pradesh

Blast and fire at a facility under construction. Police linked it to hydrogen leakage. Controlled in about 30 minutes; HPCL reported no casualties.

Times of India · 20 Sep 2025

IndianOil Mathura Refinery

12 NOV 2024 | Mathura · Uttar Pradesh

Crude-distillation-unit fire injured eight. IndianOil reported normal operations and no machinery damage. Investigation underway.

Reuters · 13 Nov 2024

IndianOil Haldia Refinery

21 DEC 2021 | Haldia, Purba Medinipur · West Bengal

Maintenance fire in the gasoline-making unit killed three and injured 44, IndianOil reported.

Reuters · 22 Dec 2021

Reliance Jamnagar Refinery

24 NOV 2016 | Moti Khavdi, Jamnagar · Gujarat

Maintenance flash fire killed two and injured eight in the updated report. Police cited a gas leak; Reliance reported normal refinery operations.

NDTV · 25 Nov 2016

Selected reports; figures follow the linked sources. These incidents do not establish EC 43 performance.